FORM APPROVED Division of Health Care Facilitie. STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X8) DATE SURVEY IDENTIFICATION NUMBER: COMPLETED 01 - MAIN BUILDING OF A. BUILDING B. WING. TN2101 10/04/2010 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 825 FISHER AVE P O BOX 549 NHC HEALTHCARE, SMITHVILLE SMITHVILLE, TN 37186 SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUSTI BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PROVIDER'S FLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (X4) ID PREFIX TAG (XS) COMPLETE PREFIX TAG DATE DEFICIENCY N B32 1200-8-6-.08(2) Building Standards N 832 Maintenance Supervisor will remove all 10/22/10 loose plaster from the ceiling and repaint (2) The condition of the physical plant and the the ceiling. On October 5, 2010, we overall nursing home environment must be replaced ceiling tiles in the kitchen's developed and maintained in such a manner that chemical room. Maintenance Supervisor the safety and well-being of residents are will visually check ceilings in kitchen for assured. stain and loose plaster once a week for one (1) month and once a month for three (3) months. This Rule is not met as evidenced by: Based on observations it was determined the facility failed to comply with the State Building Standards. The findings include: (1) Observation of the kitchen's dry storage room on 10/4/10 at 9:27 AM, revealed the ceiling's plaister was loose from the ceiling. Tennessee Department of Health 1200-8-6-,08(2) (2) Observation of the kitchen's chemical room on 10/4/10 at 9:35 AM, revealed a water stain ceiling tile. TDOH 1200-8-6-,08(2) These findings were acknowledged by the Administrator and verified by the Director of Maintenance at the exit conference on 10/4/10.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

THILE

If continuation sheet 1 of 1

Division of Health Care Facilities